

# Shafts

## Surface Fully Plated Type

Surface treatment is also applied to shaft ends.

Type					D Tol.	Material	Hardness	Surface Treatment
Solid	One End Tapped	Both Ends Tapped	One End Stepped and Tapped	One End Stepped, Both Ends Tapped				
PSFCJ	PSFCT	PSFCW	PSFCG	PSFCA	g6	SUJ2	Effective Hardened Depth of Induction Hardening $\geq$ P.142 SUJ2.58HRC-	Electroless Nickel Plating

The surface roughness of D part is  $\sqrt{0.4}$ .

**PSFCJ** (Solid Type)  
**PSFCT** (One End Tapped)  
**PSFCW** (Both Ends Tapped)  
**PSFCG** (One End Stepped and Tapped)  
**PSFCA** (One End Stepped, Both Ends Tapped)

**RoHS**  
 L Dimension Tolerance, Circularity, Straightness, Perpendicularity, Concentricity and Changes in Hardness  $\geq$  P.141  
 Annealing may lower hardness at shaft end machined areas (effective thread length + approx. 10mm).  
 Shafts may have centering holes at end faces depending on shapes.

Use "Oil-Free Bushings" for sliding applications. P.415-436 (Using rolling ball elements such as linear ball bushings on electroless nickel plated shafts may result in flaking of the nickel plating layer.)

### Solid / One End Tapped / Both Ends Tapped

Part Number	1mm Increments		Selection		C
	Type	D	L	M	
Solid Type PSFCJ	8	20~800	3 4 5	3 4 5	0.5 or Less
	10	20~800	3 4 5 6	3 4 5 6	
	12	20~1000	4 5 6 8	4 5 6 8	
One End Tapped PSFCT	15	25~1000	4 5 6 8 10	4 5 6 8 10	1.0 or Less
	20	30~1000	4 5 6 8 10 12	4 5 6 8 10 12	
Both Ends Tapped PSFCW	25	35~1000	4 5 6 8 10 12 16	4 5 6 8 10 12 16	1.0 or Less
	30	35~1000	6 8 10 12 16 20	6 8 10 12 16 20	
	35	35~1000	8 10 12 16 20 24	8 10 12 16 20 24	
	40	50~1000	10 12 16 20 24 30	10 12 16 20 24 30	
	50	65~1000	12 16 20 24 30	12 16 20 24 30	

For One End Tapped Type, when  $Mx2.5+4 \geq L$ , tap pilot holes may go through.  
 For Both Ends Tapped Type, when  $Mx2.5+4x2 \geq L$ , tap pilot holes may go through and the effective length of the smaller tap part may be shortened.

### One End Stepped and Tapped / One End Stepped, Both Ends Tapped

Part Number	1mm Increments		Selection		(Y)Max.	R	C	
	Type	D	L	F				P
One End Stepped and Tapped PSFCG	8	25~798		6	3	3 4 5	800	0.5 or Less
	10	25~798		6~8	3 4 5	3 4 5 6	800	
	12	25~998		6~10	3 4 5 6	4 5 6 8	1000	
	15	25~998		6~13	3 4 5 6 8 10	4 5 6 8 10	1000	
One End Stepped, Both Ends Tapped PSFCA	20	25~998	$2 \leq F \leq P \times 4$	8~17	4 5 6 8 10 12	4 5 6 8 10 12	1000	1.0 or Less
	25	25~998		8~22	4 5 6 8 10 12 16	4 5 6 8 10 12 16	1000	
	30	25~998		9~27	5 6 8 10 12 16 20 24	6 8 10 12 16 20	1000	
	35	25~998		9~32	5 6 8 10 12 16 20 24	8 10 12 16 20 24	1000	
	40	25~998		11~37	6 8 10 12 16 20 24 30	10 12 16 20 24 30	1000	
50	25~998	11~47	6 8 10 12 16 20 24 30	12 16 20 24 30	1000			

For One End Stepped and Tapped Type, when  $P \geq M+3$  and  $Mx2.5+4 \geq Y$ , tap pilot holes may go through.  
 For One End Stepped, Both Ends Tapped Type, when  $P \geq M+3$  and  $Mx2.5+4x2 \geq Y$ , tap pilot holes may go through and the effective length of the smaller tap part may be shortened.

Ordering Example

Part Number	-	L	-	F	-	P	-	M	-	N
PSFCJ20	-	75								
PSFCT20	-	525						M8		
PSFCW20	-	525						M8	-	N8
PSFCG20	-	400	-	F25	-	P16	-	M10		
PSFCA20	-	400	-	F25	-	P16	-	M10	-	N10

### Solid

Part Number	Unit Price											
	Type	D	Min. L	L51	L101	L151	L201	L301	L401	L501	L601	L801
PSFCJ	8											
	10											
	12											
	15											
	20											
	25											
	30											
	35											
	40											
	50	-										

### One End Tapped

Part Number	Unit Price											
	Type	D	Min. L	L51	L101	L151	L201	L301	L401	L501	L601	L801
PSFCT	8											
	10											
	12											
	15											
	20											
	25											
	30											
	35											
	40											
	50	-										

### One End Stepped and Tapped

Part Number	Unit Price											
	Type	D	Min. L	L51	L101	L151	L201	L301	L401	L501	L601	L801
PSFCG	8											
	10											
	12											
	15											
	20											
	25											
	30											
	35											
	40											
	50	-										

Alterations

Part Number	-	L	-	M	-	N	-	(SC FC-etc.)
PSFCW20	-	525	-	M8	-	N8	-	SC0

Surface treatment will be also applied to altered areas.  
 Alterations may lower hardness. See  $\geq$  P.142.  
 When selecting multiple alteration additions, the distance between machined areas should be greater than 2mm.  $\geq$  P.144

Alterations	Alteration to L dimension tolerance	Wrench Flats	Set Screw Flat	Fine Tap																																										
	Code	LKC	SC	FC	MSC, NSC																																									
Spec.	Changes L tolerance. (Ordering Code) LKC L < 200 ... $\pm 0.03$ 200 < L < 500 ... $\pm 0.05$ L > 500 ... $\pm 0.1$ L dimensions can be specified in 0.1mm increment for LKC. Not applicable to One End Threaded with O.D. same as Shaft O.D.	Adds wrench flats. (Ordering Code) SC5 SC = 1mm Increment SC + $\phi_1$ : L, SC > 0 <table border="1"> <tr> <th>D</th> <th>W</th> <th><math>\phi_1</math></th> </tr> <tr> <td>8</td> <td>7</td> <td>8</td> </tr> <tr> <td>10</td> <td>8</td> <td>8</td> </tr> <tr> <td>12</td> <td>10</td> <td>8</td> </tr> <tr> <td>15</td> <td>13</td> <td>10</td> </tr> <tr> <td>20</td> <td>17</td> <td>10</td> </tr> </table>	D	W	$\phi_1$	8	7	8	10	8	8	12	10	8	15	13	10	20	17	10	Adds a screw flat. (Ordering Code) FC10-E8 FC, E=1mm Increment FC < D x 3 When 1.5xD-FC, FC < L/2 E=0 or E $\geq$ 2 <table border="1"> <tr> <th>D</th> <th>h</th> </tr> <tr> <td>8-15</td> <td>1</td> </tr> <tr> <td>20-40</td> <td>2</td> </tr> <tr> <td>50</td> <td>3</td> </tr> </table>	D	h	8-15	1	20-40	2	50	3	Changes tapped threads to fine tapped threads shown in the table below. (Ordering Code) MSC14 Specify in reference to D dimensions for One End Threaded Shafts; P dimensions for One End Stepped and Tapped Shafts. <table border="1"> <tr> <th>D, P</th> <th>MSC, NSC</th> </tr> <tr> <td>12</td> <td>8</td> </tr> <tr> <td>15</td> <td>8 10</td> </tr> <tr> <td>20</td> <td>8 10 12 14</td> </tr> <tr> <td>25-35</td> <td>8 10 12 14 18</td> </tr> <tr> <td>40</td> <td>10 12 14 18</td> </tr> <tr> <td>50</td> <td>10 12 14 18</td> </tr> <tr> <td>Pitch</td> <td>1.0 1.25 1.5</td> </tr> </table> Specify M dimensions with MSC. M dimension is equal to MSC.	D, P	MSC, NSC	12	8	15	8 10	20	8 10 12 14	25-35	8 10 12 14 18	40	10 12 14 18	50	10 12 14 18	Pitch	1.0 1.25 1.5
D	W	$\phi_1$																																												
8	7	8																																												
10	8	8																																												
12	10	8																																												
15	13	10																																												
20	17	10																																												
D	h																																													
8-15	1																																													
20-40	2																																													
50	3																																													
D, P	MSC, NSC																																													
12	8																																													
15	8 10																																													
20	8 10 12 14																																													
25-35	8 10 12 14 18																																													
40	10 12 14 18																																													
50	10 12 14 18																																													
Pitch	1.0 1.25 1.5																																													